



# Sanitary Sewer Overflow Annual Report

## Division of Surface Water

**Date:** 03/16/2020

**Facility Name:** Steubenville WWTP

**Ohio NPDES Permit Number:** OPD00014\*MD

**Period Covered by Report:** 01/01/2019 - 12/31/2019

**Contact Person**

**Name:** CHARLES MURPHY SR.

**Title:** UTILITY DIRECTOR

**Mailing Address:** 100 North Water Street

**City:** Steubenville

**State:** OH

**Zip Code:** 43952

**Country:** USA

**Sanitary Sewer Overflows Spreadsheet(attachment) :** 2019 SSO Overflow.xlsm

**Water In Basement Occurrences Spreadsheet(attachment) :** 2019 WIB Occurrences.xlsm

**Narrative analysis of WIB patterns by location, frequency and cause:** *Lauretta Drive: Found roots in the line and a portion of the pipe was broken. Replaced the broken portion of the pipe and removed the roots from the line.*

*Whitehaven Blvd.: Found and removed roots from the line.*

**Additional Attachments :**

### Certification

*I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately responsible for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.*

**Name:**

Charles W Murphy, Sr

**Title:**

Assistant Superintendant

**Signature(Electronically submitted by):**

Charles W Murphy, Sr (User ID: SteubenvilleWWTP )

**Submission Date:**

03/16/2020





